

Mountain Ave.

Looking west at Jarvis

Poor condition in the left gutter continues.
Similar overall condition compared to last photo.
Extent of reconstruction will become evident upon
milling of the roadway.

Multiple trenches cause an unpleasant ride.




Mountain Ave.

Looking west at Kilburn St.

Poor condition of left gutter continues.

Condition improves west of Kilburn St.




Mountain Ave.

Looking west to Lambert St.

Gutter condition improves.


Longitudinal cracks are visible but lack extensive settlement, therefore majority of road base is assumed to be firm enough to support milling and paving of the roadway.



Mountain Ave.

Looking west towards limit of repaving at Seaview

Road in decent condition, shows cracking but settlement is not substantial.
Slight alligator cracking in right gutter shown, but not nearly as severe as the left gutter closer to Broadway.



2/3/2016