

PHASE 2 – FEASIBILITY ANALYSIS

HICHBORN STREET

(R.B. PARKWAY TO LEE BURBANK HWY)

This short section of Hichborn Street requires little to no attention at this time. Any minor repairs that require immediate attention could be addressed by the Public Works Department.

At the top of the roadway there is alligator cracking and pothole repairs have been made. Moving further down the road the alligator cracking ceases and the surface is in good shape (refer to photos). Perhaps in three or four years we should re-visit the street and determine if re-surfacing might be necessary.

The bituminous sidewalk, with the exception of the stretch between # 6 and # 54 Hichborn, and a serious tripping hazard in front of 6-8 Hichborn Street, are in fair to good condition. We have already contacted Paul Argenzio and advised him of the tripping hazard in front of #6 - # 8 Hichborn Street (see attached photos). In our opinion the area between 6 and 54 Hichborn Street could also be addressed by the Public Works Department.

There is both concrete and granite curbing running the length of the roadway. There are sections where the curb is either rolled or sunken.

If and when it is decided to rehabilitate this section of Hichborn Street; we suggest the following;

1. mill and repave the roadway
2. place existing curbing with new granite curbing.
3. Remove existing asphalt sidewalks and replace with new asphalt sidewalks

Hichborn Street

Looking towards 1A

Alligator cracking turning into potholes close to 1A



2/2016

Hichborn Street

Looking towards 1A

Photo shows failing gas trench & longitudinal and transverse cracking.

Granite curb and sidewalks in decent condition.




Hichborn Street

Heading south, looking north towards 1A

Grass trench in good shape, roadway beginning to break, but not nearly as bad as the 1A intersection.

Asphalt sidewalks in poor condition.



Hichborn Street

Photo shwoing sediment control left in catch basin,
most likely from gas main installation.

Sediment controls likely casusing poor drainage function
on the street.



Hichborn Street

Photo highlighting various curbing materials on the street and section of sidewalk in poor condition.



Hichborn Street

Photo highlighting worst section of roadway close to 1A

